



J-5000型差壓錶被廣泛應用於測量風扇和鼓風機的壓力,篩檢程式阻力,風速,爐壓,孔板差壓,同時也用於燃燒過程中的空氣煤氣比值控制及自動閥控制,以及醫療保健設備中的血壓和呼吸壓力監測。

**外殼材質：**壓模鑄鋁或含尼龍的ABS塑膠。

環境溫度: -7 ~ 60℃

<b>壓力範圍 PRESSURE RANGE:</b>							
<b>Model</b>	<b>Range Inches of Water</b>	<b>Model</b>	<b>Range PSI</b>	<b>Model</b>	<b>Range MM of Water</b>	<b>Model</b>	<b>Range, kPa</b>
J-5000-00N+.. J-5000-00+.. J-5000-0+.. J-5001 J-5002 J-5003 J-5004 J-5005 J-5006 J-5008 J-5010 J-5012 J-5015 J-5020 J-5025 J-5030 J-5040 J-5050 J-5060 J-5080 J-5100 J-5120 J-5150 J-5160 J-5180 J-5250	.05-0-.2 0-.25 0-.50 0-1.0 0-2.0 0-3.0 0-4.0 0-5.0 0-6.0 0-8.0 0-10 0-12 0-15 0-20 0-25 0-30 0-40 0-50 0-60 0-80 0-100 0-120 0-150 0-160 0-180 0-250	J-5201 J-5202 J-5203 J-5204 J-5205 J-5210* J-5215* J-5220* J-5230**	0-1 0-2 0-3 0-4 0-5 0-10 0-15 0-20 0-30	J-5000-6MM+.. J-5000-10MM+.. J-5000-15MM J-5000-25MM J-5000-30MM J-5000-50MM J-5000-80MM J-5000-100MM J-5000-125MM J-5000-150MM J-5000-200MM J-5000-250MM J-5000-300MM	0-6 0-10 0-15 0-25 0-30 0-50 0-80 0-100 0-125 0-150 0-200 0-250 0-300	J-5000-0.5KPA J-5000-1KPA J-5000-1.5KPA J-5000-2KPA J-5000-2.5KPA J-5000-3KPA J-5000-4KPA J-5000-5KPA J-5000-8KPA J-5000-10KPA J-5000-15KPA J-5000-20KPA J-5000-25KPA J-5000-30KPA	0-0.5 0-1 0-1.5 0-2 0-2.5 0-3 0-4 0-5 0-8 0-10 0-15 0-20 0-25 0-30
		<b>Model</b>	<b>Range, CM of Water</b>	<b>Zero Center Ranges</b>		<b>Zero Center Ranges</b>	
		J-5000-15CM J-5000-20CM J-5000-25CM J-5000-50CM J-5000-80CM J-5000-100CM J-5000-150CM J-5000-200CM J-5000-250CM J-5000-300CM	0-15 0-20 0-25 0-50 0-80 0-100 0-150 0-200 0-250 0-300	J-5300-6MM+.. J-5300-10MM+.. J-5300-20MM+..	3-0-3 5-0-5 10-0-10	J-5300-1KPA J-5300-2KPA J-5300-2.5KPA J-5300-3KPA	5-0-5 1-0-1 1.25-0-1.25 1.5-0-1.5
		<b>Model</b>	<b>Range, Pa</b>	<b>Model</b>	<b>Range, Pa</b>		
		J-5000-60NP+.. J-5000-60PA+.. J-5000-100PA+.. J-5000-125PA+.. J-5000-250PA J-5000-300PA J-5000-500PA J-5000-750PA J-5000-1000PA	10-0-50 0-60 0-100 0-125 0-250 0-300 0-500 0-750 0-100x10	<b>Zero Center Ranges</b>			
<b>Zero Center Ranges</b>		J-5300-4CM J-5300-10CM J-5300-30CM	2-0-2 5-0-5 15-0-15	<b>Model</b>	<b>Range, Pa</b>		
J-5300-00+.. J-5300-0+.. J-5301 J-5302 J-5304 J-5310 J-5320 J-5330	0.125-0-0.125 .25-0-.25 5-0-.5 1-0-1 2-0-2 5-0-5 10-0-10 15-0-15		<b>Accuracy +/-3% Accuracy +/-4%</b>	<b>Zero Center Ranges</b>			
				J-5300-60PA+.. J-5300-100PA+.. J-5300-120PA J-5300-200PA J-5300-250PA J-5300-300PA J-5300-500PA J-5300-1000PA	30-0-30 50-0-50 60-0-60 100-0-100 125-0-125 150-0-150 250-0-250 500-0-500		

TEL:(02)26940177 (02)26949824 FAX:(02)26946663  
www.hsinjeng.com.tw E-mail : hsin.jeng@msa.hinet.net